


Figure 3A






Figure 4A




Figure 4B

CLIENT DHCP LEASE NEGOTIATIONS 404





Figure 5A

558

562






Figure 6B





Figure 6C






Figure 7B





Figure 7C

14 / 22
INTERNAL PHONE to INTERNAL PHONE RTP FLOW






Figure 8B




Figure 8C

PHONE to MEDIA GATEWAY RTP FLOW 490B




Figure 9A




Figure 9B

and report as our labella his his his






Figure 9C








Figure 11